



O2 Sensors for Stationary Industrial Engines



2001 Two Wire Non-Heated: Primary Application Altronic™ EPC 50, EPC 100 AFR's, Waukesha and Continental Control AFR's

Replaces Altronic™ 610621, Bosch™ 12028, CC Controls™ 50505019, Delco™ AFS23, Denso™ 234-2001 and Waukesha™ 740106E/ 740105D



4001 4 Wire Heated Sensor W/ Round pin Connector

Replaces Bosch™ 15718



4003 4 Wire, 6 Ohm Heated Sensor - Oval Connector- Body Ground Primary Application Emit™ AFR's

Replaces Bosch™ 15703



4006 4 Wire, 6 Ohm Heated Sensor - Oval Connector- Body Ground Primary Application Emit™ AFR's

Replaces Bosch™ 13026



4011 Cummins Bus AFR's 4 wire heated Sensor

Replaces Cummins numbers 4954893, 5341762 (Requires Cummins adaptor 5340715)



5001 Caterpillar™ 3400 Engines 6 pin/5 Wire Wide Band Sensor

Replaces Cat™ 196-5391



5002 Caterpillar™ 3500 Engines 6 pin/5 Wire Wide Band Sensor

52" Shielded Body

Replaces Cat™ 141-2494



5008 Gill and Emit AFR's 6 pin/5 Wire Wide Band Sensor

Replaces Bosch 17014, Emit 13019



5009 Altronic EPC150, Cummins and Waukesha AFR's 6 pin/5 Wire Wide Band Sensor

Replaces Altronic 610013, Cummins 4001675



5010 Waukesha AFR's 6 pin/5 Wire Wide Band Sensor

Replaces Waukesha A740132



5011 6 pin/5 Wire Wide Band Sensor Replaces Bosch 2810044135



5012 6 pin/5 Wire Wide Band Sensor Replaces Bosch 258006065



5013 6 pin/5 Wire Wide Band Sensor Replaces Bosch 258007032



5014 6 pin/5 Wire Wide Band Sensor Replaces Bosch 258007151




5015 6 pin/5 Wire Wide Band Sensor Replaces Bosch 258007351



5016 6 pin/5 Wire Wide Band Sensor Replaces Bosch 2581041002



Features and Benefits



High Temperature Wire Protection

High Temperature O.E. Exact connectors

Steel Shell with 18MM X 1.25 Threads

Zirconia Sensor Cell W/Stainless Steel Cage

Built to Meet or Exceed OEM Specifications

Oxygen Sensor Installation Tips

Check Condition of old Sensor for signs of contamination and system problems

Check Bung Hole Threads to make sure they are in good condition

Install by hand until gasket seats and finish by tightening to Manufacturer specifications

Route leads away from high temperature exhaust components as external wires can be damaged by extreme heat

Dropped sensors may cause shock damage to the ceramic element.

Keep sensor tip clean and avoid exposure to water, oil, anticorrosion oil, grease, terminal cleaner, etc.