



Rebuilt Caterpillar® 330-5584 Actuators

Air Fuel Ratio/Throttle Actuator

Applications: G3508, G3512, G3616

Detailed Scope of Repair:

- Actuator is cleaned, disassembled, and checked for common wear
- Commonly, the front sealed bearings wears, in turn causing the drive shaft to wobble and cause timing issues
- Sealed bearings are replaced along with other necessary seals
- Shaft is then re-aligned and timed
- The electronics of the unit are then tested to ensure there are no issues and fixed if needed
- Units are re-assembled and tested one final time before packaging

Currently, this actuator program is a core repair and return program, so we are looking for as many cores as possible so we can stock our shelves with tested, repaired units for our customers.

We are also willing to purchase cores outright if you are not interested the repair and return program.

Contact us for a quote today.

P.N. ACT-5584-R

Caterpillar® Ref: 330-5584, 20R-5449
328-0754, 20R-3112



4618 Airpark Blvd. Duluth, MN 55811

sales@tripowertrading.com

(TF) 877-239-2491

(O) 218-727-4220